
















8116










8116N

NR	ELEMENT	8116N
E1		1
E2		1
E3		1
E4		1
E5		1
E6		1


NR	ELEMENT	8116N
E7		1
E8		1
E9		1
E10		1
E11		1
E12		1



8116N

Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	2
2		-	W6x60	1
21		DIN 125	8x16	1
58		-	LOCTITE	1
77		-	K3_d30_A89 _G	1
213		-	Z_NA_1	1
214		-	Z_NA_2	1



8116N





# 8116N

ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”





8116N



2

8116N








3

8116N

B25 0,7m<sup>3</sup>




min. 48H




4

8116N



5

8116N



INST\_81\_17

