









8146













8146N


NR	ELEMENT	8146N
E1	<div data-bbox="236 566 391 600" data-label="Text">D8146_1N</div> 	1
E2		1
E3		1
E4		1
E5		1



8146N

Nr	Element			Σ
1		-	S6x60	3
2		-	W6x60	1
21		DIN 125	8x16	1
26		-	S4x40	8
48		-	TE_1_A2_g4_v1	1
50		-	TE_2_A2_g4_v1	1
58		-	LOCTITE	1
77		-	K3_d30_A89_G	1
213		-	Z_NA_1	1
214		-	Z_NA_2	1



8146N



8146N




ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8146N




2

8146N



INST_81_2
INST_81_11A
INST_81_17



3

8146N

3

B25 0,4m

min. 48H

